


FINGERLESS GLOVE SIZE CHART



Measure the circumference of your hand starting about $\frac{1}{2}$ " below the fingers

	XS	S	М	L	XL
INCHES	6 - 7	7-8	8 - 9	9 - 10	10 - 11
CENTIMETERS	15 - 18	18 - 21	21 - 23	23 - 26	26 - 29

If you are unable to print this chart use the table to identify your glove size.